



MAINTENANCE SUPPLIES

CASE STUDY

Coton Lane
Tamworth
Staffs B79 8NN

DESCRIPTION

Maintenance Supplies Ltd were asked to complete concrete repairs and install a new anti-slip surface to the perimeter on No.3 PST tank. After an initial inspection, work was started to repair the damaged 100 linear metre's with an epoxy mortar on each of the tanks. Once repaired we then reinstated the anti-slip system with an Epoxy Primer incorporating a Silicon Carbide broadcast to create a hard wearing surface.

COMMENTS

On completion of the job the site contact Ray Percival called the Maintenance Supplies office to praise the quality of the workmanship and the professionalism and attitude of the Maintenance Supplies operative's.

Obviously this is a specialist system in which we at Maintenance Supplies have competently completed. Maintenance Supplies have now completed 2 PST resurfacing jobs at Tamworth and Tideswell for Severn Trent. If we can assist you in the near future please do not hesitate to contact us.

Tom Leigh
Contract Manager
Tel.: 07966298870

MAINTENANCE SUPPLIES LTD

Brook House
101 Chelford Road
Macclesfield
Cheshire
SK10 3LQ

Phone: 01625 668777
Fax: 01625 668555
www.maintenancesuppliesltd.co.uk

CASE STUDY



MAINTENANCE SOLUTIONS FOR YOUR INDUSTRY